


# MACHINE ATTACHMENTS




Model	A mm	B mm	C mm	Kg.	Model. PLURY
ADAPTER FOR QUICK COUPLING 1/4 ton	/	/	/	/	W1 9.0   W1 15.0
ADAPTER FOR QUICK COUPLING 4/6.5 ton	/	/	/	/	W1 27.0   W1 40.0
ADAPTER FOR QUICK COUPLING 7/15 ton	/	/	/	/	W1 65.0   W2 60.0   W2 80.0
ADAPTER FOR QUICK COUPLING 8/20 ton	/	/	/	/	W1 95.0   W2 100.0   W2 120.0
ADAPTER FOR QUICK COUPLING 18/40 ton	/	/	/	/	W2 150.0   W2 180.0




Model	A mm	B mm	C mm	Kg.	Model. PLURY
FIXED COUPLING MACHINE 1/4 ton	/	/	/	/	W1 9.0   W1 15.0
FIXED COUPLING MACHINE 4/6.5 ton	/	/	/	/	W1 27.0   W1 40.0
FIXED COUPLING MACHINE 7/15 ton	/	/	/	/	W1 65.0   W2 60.0   W2 80.0
FIXED COUPLING MACHINE 8/20 ton	/	/	/	/	W1 95.0   W2 100.0   W2 120.0
FIXED COUPLING MACHINE 18/40 ton	/	/	/	/	W2 150.0   W2 180.0



Model	A mm	B mm	C mm	Kg.	Model. PLURY
BOLTED PLATE MACHINE COUPLING 1/2 ton	390	195	10	7	W1 9.0
BOLTED PLATE MACHINE COUPLING 1.5/4 ton	410	235	10	8.5	W1 15.0
BOLTED PLATE MACHINE COUPLING 4/6.5 ton	470	280	15	16.5	W1 27.0   W1 40.0
BOLTED PLATE MACHINE COUPLING 7/15 ton	640	340	15	29	W1 65.0   W2 60.0   W2 80.0
BOLTED PLATE MACHINE COUPLING 8/20 ton	710	400	20	48	W1 95.0   W2 100.0   W2 120.0
BOLTED PLATE MACHINE COUPLING 18/40 ton	920	450	20	70	W2 150.0   W2 180.0



Model	A mm	B mm	C mm	Kg.	Model. PLURY
TOK QUICK COUPLER 1/4 ton	525	103	220	29	W1 9.0   W1 15.0
TOK QUICK COUPLER 4/6.5 ton	625	120	295	53	W1 27.0   W1 40.0
TOK QUICK COUPLER 7/40 ton	805	160	480	140	W1 65.0   W2 60.0   W2 80.0 W1 95.0   W2 100.0   W2 120.0 W2 150.0   W2 180.0



Model	A mm	B mm	C mm	Kg.	Model. PLURY
TOK ADAPTER 1/4 ton	460	120	230	19,5	W1 9.0   W1 15.0
TOK ADAPTER 4/6.5 ton	570	160	290	37	W1 27.0   W1 40.0
TOK ADAPTER 7/40 ton	750	175	475	88	W1 65.0   W2 60.0   W2 80.0 W1 95.0   W2 100.0   W2 120.0 W2 150.0   W2 180.0